




**Figure 1**




**Figure 2A**




MULTICHIP CERAMIC PACKAGE 28



**Figure 2B**




DEFECTIVE PART WITH INTERMITTENT SHORT (W1008)




Ohms, Vcc to Ground

**Figure 3A**




PART W1008 AFTER REMOVAL OF SHORT




Ohms, Vcc to Ground


**Figure 3B**




DEFECTIVE EPOXY CONTACT ON PART (W1020)



**Figure 4**





PART W1020 AFTER REPAIR OF DEFECTIVE EPOXY CONTACT




Ohms, Vcc to Ground

**Figure 5**



**FIG. 6A**





**FIG. 6B**

